

## Safety Notice to all Star Cool Service Providers

Date: 01 Nov 2011  
Page: 1/1

There have been several bulletins and reports from machinery manufacturers and shipping lines in relation to the unfortunate incidences of compressor ruptures, spontaneous combustion of refrigerant and system contamination.

The messages contained in these bulletins focus on the need to identify and quarantine suspect equipment, as well as ensuring that refrigerants are procured from genuine, reliable sources.

Maersk Container Industry supports these initiatives, particularly during the present situation where the cause and substance/s involved are yet to be determined.

Once the nature of the contaminant has been determined, it should then be possible to develop a safe procedure to test for the substance/s and if the system is contaminated, find a safe procedure for removal, system cleaning and to understand which components may have been affected.

We will update you with further information once it becomes available.

Peter Tanner  
Director, Global Service  
Maersk Container Industry, Star Cool  
[pnt@maerskbox.com](mailto:pnt@maerskbox.com)  
[www.starcool.dk](http://www.starcool.dk)